


BMW 3: 1GGX286

Vinnumber:	WBA3K91090F932735	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	5/02/2014	Fiscalpower:	
Expertise Mileage:	99892	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	A FAIRE	Parking lot:	2723
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	Tow bar fixed
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/92 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1109,80
-------------------	----------------

Wheel cover F L, Scratch(es), E - Replace	30,00
---	--------------



Door panel R L, Tear, Acceptable	0,00
----------------------------------	-------------



Interior, Stain, Cleaning 100,00



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Missing, E - Replace 240,00



Roof, Dent(s), PDR - Knock out without painting 142,20



Wheel cover R R, Scratch(es), E - Replace 30,00



Headlight R, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Dent(s), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00



Wheel cover F R, Scratch(es), E - Replace 30,00



Roof, Chemical pollution, 67 - Polish 0,00

No pictures to display

Wheel aperture R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Dent(s), Acceptable 0,00

No pictures to display

Door F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Door panel R R, Scratch(es), E - Replace	114,00
--	--------

