


MERCEDES E: 1HHK269

Vinnnumber:	WDD2120051B061047	Versionname:	E BER 200CDI BE 136PK
First Registrationdate:	24/07/2014	Fiscalpower:	
Expertise Mileage:	136918	Power Kw:	100
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3330
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/17/92 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	3089,90
-------------------	----------------

Bonnet, Dent(s), PDR - Knock out without painting	63,00
---	--------------



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	---------------



Door F L, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Door F R, Scratch(es), LI - Repair and paint (complete) 382,02



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wing R R, Scratch(es), It - Spot repair 115,56




Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Console storage compartment, Crack, E - Replace 47,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Tailgate, Chemical polution, LI - Repair and paint (complete) 362,02



Windscreen, Repaired, Acceptable 0,00



Alloy rim F R polished, Rust, Acceptable	0,00
--	------

No pictures to display

Glove box cover, Crack, E - Replace	336,00
-------------------------------------	--------



Sill outer L, Dent(s), It - Spot repair	115,56
---	--------



Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	302,16
---	--------

