



MERCEDES A: 1GIV687			
Vinnumber:	WDD1760121J245887	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	19/02/2014	Fiscalpower:	
Expertise Mileage:	72828	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3503
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	No GPS
Type of Lining:	Lining leather
Type of climate control:	Manual climate control













Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/40/18/92 V LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			803,60
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)			211,80



Windscreen, Repaired, Acceptable	0,00
----------------------------------	------

<i>No pictures to display</i>		
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bumper F, Scratch(es), LI - Repair and paint (complete)		211,80
		
		
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Rearview mirror housing L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		