


**OPEL Insignia: 1GMB809**

Vinnnumber:	<b>WOLGM5ER3E1085813</b>	Versionname:	<b>INSIGNIA BER ecoFLEX Business 120PK</b>
First Registrationdate:	<b>7/03/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>178320</b>	Power Kw:	<b>88</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>UITVOEREN</b>	Parking lot:	<b>2209</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Seats electric F L
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/97 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**






















Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	454,96
-------------------	--------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------



Sunblind L, Broken, E - Replace	25,00
---------------------------------	-------

		Wing F R, Rust, It - Spot repair	115,56
		Tailgate, Dent(s), Acceptable	0,00
		Door R R, Dent(s), Acceptable	0,00
		Bumper R, Dent(s) and scratch(es), Acceptable	0,00
			0,00
		Roof pillar R, Dent(s), Acceptable	0,00
		Roof, Dent(s), PDR - Knock out without painting	102,60
		Wing R L, Dent(s), Acceptable	0,00
		Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
			0,00
Maintenance, Maintenance, Execute	0,00		

