







### SKODA Superb: 1HER916

Vinnumber: TMBJE73T4F9010376 First Registrationdate: 2/07/2014 Expertise Mileage: 85024 Bodytype: Gearbox: MAN 6 VIT Transmission: Front Fueltype: Diesel Maintenance ок Battery functioning Yes Number of doors 5 Number of seats 5 Number head rests 5 Rims summer **Aluminium** Category Passenger Car Oil level

SUPERB COMBI Elegance Versionname: 140PK Fiscalpower: Power Kw: 103 Body color Silver Paint type Metalic Rims summer Aluminium Oil level ок Parking lot 3322

#### Options

Radio CD Steats R heated GPS storage Central consol F GPS storage HD Luggage cover Front parking sensors Windows electric F Windows electric R Rear parking sensors

OK

Cruise Control Steering wheel multifunctional

Registration Certificate Car (BE)

Seats F heated

Type of headlighting Headlighting Xenon Type of GPS GPS big screen color Type of Lining Lining leather Type of climate Autom climate control

# **Limited Technical Inspection**

Airco functioning	ок	Battery functioning	Yes
Tires wear profile	ок	Power steering	Yes
Idle position	ок	Sound engine	ОК
Engine startingtime	ок	Clutch test	ОК
Exhaust gass	ок	Wiper fluid level	ок
Handbrake	ок	Transmission	ОК
		Lighting	ОК
		Wiperblades	ОК

## Degree of wear

225/40/18/91 V LightMetal Fr.R. Continental: 3 mm Summer tyres: Continental: 3 mm Re.R. Re.L. Continental: 4 mm Continental: 4 mm

## Assistance equipment

Spare wheel	<b>Yes</b> Jack	Yes
Total cost ex VAT		2098,08
Wing R L, Scratch(es), LI - Repair and paint (complete)		369.84













Ignition key, Missing, E - Replace	150,00
No pictures to display	
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00





Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	Rearview mirror housing	L, Scratch(es), LI - R	epair and paint (c	complete)
--	-------------------------	------------------------	--------------------	-----------

115,56





Alloy rim R R polished, Rust, Acceptable

0,00





Boot carpet, Stain, Cleaning

12,50





Wing F L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), LI - Repair and paint (complete)	382,02





Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16







Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00





Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84

