



VOLKSWAGEN Golf: 1FPQ760

Vinnnumber:	WVWZZZAUZEW105925	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	17/09/2013	Fiscalpower:	
Expertise Mileage:	148821	Power Kw:	77
Bodytype:		Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 22200 KM	Parking lot:	1123
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1357,84
Rearview mirror housing R, Scratch(es), Acceptable	0,00




Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Rocker panel inner F L, Dent(s), LI - Repair and paint (complete) 115,56



Door F R, Dent(s), Acceptable 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Scratch(es), Acceptable 0,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Bumper F, Hole, Le - Replace and paint 0,00



Door panel F L, Broken, E - Replace 114,00



Door R R, Dent(s) and scratch(es), Acceptable 0,00



Rocker panel inner F R, Dent(s), Acceptable 0,00



Floor covering F L, Hole, E - Replace 252,00



Grill frame, Broken, E - Replace 54,60



Door F L, Dent(s), Acceptable 0,00

