



## VOLKSWAGEN TIGUAN: 1DUR320

|                         |                         |              |   |
|-------------------------|-------------------------|--------------|---|
| Vinnnumber:             | <b>WVGZZ5NZDW018673</b> | Versionname: | <b>TIGUAN Trend&amp;Fun BM Tech.110PK</b> |
| First Registrationdate: | <b>3/09/2012</b>        | Fiscalpower: |   |
| Expertise Mileage:      | <b>162950</b>           | Power Kw:    | <b>81</b>                                 |
| Bodytype:               |                         | Body color:  | <b>Grey</b>                               |
| Gearbox:                | <b>MAN 6 VIT</b>        | Paint type:  | <b>Metalic</b>                            |
| Transmission:           | <b>Front</b>            | Rims summer: | <b>Aluminium</b>                          |
| Fueltype:               | <b>Diesel</b>           | Oil level:   | <b>OK</b>                                 |
| Maintenance:            | <b>OK</b>               | Parking lot: | <b>3308</b>                               |
| Battery functioning:    | <b>Yes</b>              |              |   |
| Number of doors:        | <b>5</b>                |              |   |
| Number of seats:        | <b>5</b>                |              |   |
| Number head rests:      | <b>5</b>                |              |   |
| Rims summer:            | <b>Aluminium</b>        |              |   |
| Category:               | <b>Passenger Car</b>    |              |   |
| Oil level:              | <b>OK</b>               |              |   |

## Options

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Sun Roof electric     |                   |
| GPS storage                    |                              | Panoramic roof        |                   |
| GPS storage                    | <b>HD</b>                    | Central consol F      |                   |
| Windows electric F             |                              | Luggage cover         |                   |
| Windows electric R             |                              | Front parking sensors |                   |
| Steering wheel multifunctional |                              | Rear parking sensors  |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  | Type of Tow bar       | <b>No Tow bar</b> |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

## Limited Technical Inspection

|                     |           |                     |               |
|---------------------|-----------|---------------------|---------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b>    |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b>    |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>     |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>     |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>NOT OK</b> |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>     |
|                     |           | Lighting            | <b>OK</b>     |
|                     |           | Wiperblades         | <b>OK</b>     |

## Degree of wear

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/65/16/98 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Goodyear: 5 mm</b> | Fr.R. | <b>Goodyear: 5 mm</b> |
|               | Re.L.                            | <b>Goodyear: 6 mm</b> | Re.R. | <b>Goodyear: 6 mm</b> |

## Assistance equipment

|            |           |            |            |
|------------|-----------|------------|------------|
| Repair kit | <b>No</b> | Compressor | <b>Yes</b> |
|------------|-----------|------------|------------|

|   |         |
|---|---------|
| Total cost ex VAT   | 1251,58 |
| Seat cover R, Stain, Acceptable                                     | 0,00    |
| <i>No pictures to display</i>                                       |         |
| Bumper F, Scratch(es), Acceptable                                   | 0,00    |
| <i>No pictures to display</i>                                       |         |
| Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 318,35  |





Tyre repair kit, Missing, E - Replace 210,53

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Windscreen, Stone chip(s), Windscreen repair 0,00



Luggage space cover, Incomplete, Repair/replace (lump sum) 5,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Dent(s), PDR - Knock out without painting 63,00



Cigar lighter, Broken, E - Replace 18,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 318,35

