



BMW 3: 1HLY435

Vinnnumber:	WBA3D91070F407263	Versionname:	3 BER 316d 116PK
First Registrationdate:	25/08/2014	Fiscalpower:	
Expertise Mileage:	121219	Power Kw:	85
Bodytype:		Body color	Anthracite
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4622
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/94 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

	Runflat	Yes
--	---------	-----

Total cost ex VAT

	1136,74
--	---------

Protection plate M, Strained , E - Replace

	84,00
--	-------




Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Seat cover F L, Tear, Acceptable

0,00



Tailgate, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Dent(s), PDR - Knock out without painting

63,00



Wing R L, Dent(s), PDR - Knock out without painting

102,60



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper corner R R, Scratch(es), It - Spot repair

115,56



Rocker panel inner R R, Scratch(es), Acceptable

0,00

No pictures to display