



|                                   |                   |              |                    |
|-----------------------------------|-------------------|--------------|--------------------|
| MERCEDES B: 1FSY383               |                   |              |                    |
| Vinnnumber:                       | WDD2462121J211603 | Versionname: | B 180 CDI BE 109PK |
| First Registrationdate:           | 15/10/2013        | Fiscalpower: |                    |
| Expertise Mileage:                | 67153             | Power Kwr:   | 80                 |
| Bodytype:                         | Hatchback         | Body color   | Light Blue         |
| Gearbox:                          | MAN 6 VIT         | Paint type   | Metalic            |
| Transmission:                     | Front             | Rims summer  | Aluminium          |
| Fueltype:                         | Diesel            | Oil level    | OK                 |
| Battery functioning               | Yes               | Parking lot  | 2621               |
| Number of doors                   | 5                 |              |                    |
| Number of seats                   | 5                 |              |                    |
| Number head rests                 | 5                 |              |                    |
| Rims summer                       | Aluminium         |              |                    |
| Category                          | Passenger Car     |              |                    |
| Oil level                         | OK                |              |                    |
| Registration Certificate Car (BE) | Yes               |              |                    |

|                                |                        |
|--------------------------------|------------------------|
| Options                        |                        |
| Radio CD                       | Sun Roof electric      |
| Windows electric F             | Central consol F       |
| Windows electric R             | Luggage cover          |
| Cruise Control                 |                        |
| Steering wheel multifunctional |                        |
| Radio multimedia               |                        |
| Type of headlighting           | Headlighting Halogen   |
| Type of GPS                    | No GPS                 |
| Type of Lining                 | Lining fabrics         |
| Type of climate control        | Manual climate control |

|                              |    |                     |     |
|------------------------------|----|---------------------|-----|
| Limited Technical Inspection |    |                     |     |
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Power steering      | Yes |
| Idle position                | OK | Sound engine        | OK  |
| Engine startingtime          | OK | Clutch test         | OK  |
| Exhaust gass                 | OK | Wiper fluid level   | OK  |
| Handbrake                    | OK | Transmission        | OK  |
|                              |    | Lighting            | OK  |
|                              |    | Wiperblades         | OK  |

|                |                           |                |       |                |
|----------------|---------------------------|----------------|-------|----------------|
| Degree of wear |                           |                |       |                |
| Summer tyres:  | 205/55/16/91 H LightMetal |                |       |                |
|                | Fr.L.                     | Yokohama: 5 mm | Fr.R. | Yokohama: 5 mm |
|                | Re.L.                     | Yokohama: 5 mm | Re.R. | Yokohama: 5 mm |

|                                                              |     |            |         |
|--------------------------------------------------------------|-----|------------|---------|
| Assistance equipment                                         |     |            |         |
| Repair kit                                                   | Yes | Compressor | Yes     |
| Total cost ex VAT                                            |     |            | 1481,95 |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) |     |            | 95,00   |



|                                         |        |
|-----------------------------------------|--------|
| Bumper R, Crack, Le - Replace and paint | 651,00 |
|-----------------------------------------|--------|

|                                                                                    |                                                                                    |                                                                     |        |
|------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|---------------------------------------------------------------------|--------|
|    |    | Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |
|   |   | Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 318,35 |
|   |   | Alloy rim R R, Scratch(es), LI - Repair and paint (complete)        | 95,00  |
|   |   | Bumper moulding R L, Missing, E - Replace                           | 14,40  |
|  |  | Sill outer R, Scratch(es), Acceptable                               | 0,00   |
| No pictures to display                                                             |                                                                                    |                                                                     |        |