



SKODA Octavia: 1HFB560			
Vinnnumber:	TMBJG7NE5E0228127	Versionname:	OCTAVIA COMBI Ambition
First Registrationdate:	4/07/2014	Fiscalpower:	105PK
Expertise Mileage:	156302	Power Kw:	77
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3407
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		
Options			
Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK
Degree of wear			
Summer tyres:	205/55/16/91 H LightMetal		
	Fr.L.	Michelin: 4 mm	Fr.R.
			Michelin: 4 mm
	Re.L.	Continental: 6 mm	Re.R.
Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1657,63
Door F R, Dent(s), Acceptable			0,00
No pictures to display			
Roof pillar R, Dent(s), PDR - Knock out without painting			63,00
			
Tailgate, Dent(s), PDR - Knock out without painting			63,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Bumper F, Stone chip(s), Acceptable

0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20

