



|                         |                   |              |                       |
|-------------------------|-------------------|--------------|-----------------------|
| OPEL Astra: 1FBE104     |                   |              |                       |
| Vinnnumber:             | W0LPD8EW4D8054387 | Versionname: | ASTRA BRE ecoFL Enjoy |
| First Registrationdate: | 14/05/2013        | Fiscalpower: | Active St/St 110PK    |
| Expertise Mileage:      | 170049            | Power Kw:    | 81                    |
| Bodytype:               | Break             | Body color   | Black                 |
| Gearbox:                | MAN 6 VIT         | Paint type   | Metalic               |
| Transmission:           | Front             | Rims summer  | Steel                 |
| Fueltype:               | Diesel            | Oil level    | OK                    |
| Battery functioning     | Yes               | Parking lot  | 2729                  |
| Number of doors         | 5                 |              |                       |
| Number of seats         | 5                 |              |                       |
| Number head rests       | 5                 |              |                       |
| Rims summer             | Steel             |              |                       |
| Category                | Passenger Car     |              |                       |
| Oil level               | OK                |              |                       |

|                                |                        |
|--------------------------------|------------------------|
| Options                        |                        |
| Radio CD                       | Luggage cover          |
| Windows electric F             | Rear parking sensors   |
| Cruise Control                 |                        |
| Steering wheel multifunctional |                        |
| Radio multimedia               |                        |
| Type of headlighting           | Headlighting Halogen   |
| Type of GPS                    | GPS big screen color   |
| Type of Lining                 | Lining fabrics         |
| Type of climate control        | Manual climate control |

|                              |    |                     |     |
|------------------------------|----|---------------------|-----|
| Limited Technical Inspection |    |                     |     |
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Power steering      | Yes |
| Idle position                | OK | Sound engine        | OK  |
| Engine startingtime          | OK | Clutch test         | OK  |
| Exhaust gass                 | OK | Wiper fluid level   | OK  |
| Handbrake                    | OK | Transmission        | OK  |
|                              |    | Lighting            | OK  |
|                              |    | Wiperblades         | OK  |

|                |                      |                   |       |
|----------------|----------------------|-------------------|-------|
| Degree of wear |                      |                   |       |
| Summer tyres:  | 215/60/16/95 V Steel |                   |       |
|                | Fr.L.                | Continental: 3 mm | Fr.R. |
|                |                      | Continental: 3 mm |       |
|                | Re.L.                | Continental: 4 mm | Re.R. |
|                |                      | Continental: 4 mm |       |

|                       |     |      |     |
|-----------------------|-----|------|-----|
| Assistance equipment  |     |      |     |
| Emergency spare wheel | Yes | Jack | Yes |

|                               |         |
|-------------------------------|---------|
| Total cost ex VAT             | 1182,03 |
| Tailgate, Dent(s), Acceptable | 0,00    |

|                                                         |        |
|---------------------------------------------------------|--------|
| No pictures to display                                  |        |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |



|                                                       |        |
|-------------------------------------------------------|--------|
| Bonnet, Scratch(es), LI - Repair and paint (complete) | 290,08 |
|-------------------------------------------------------|--------|



|                                                                                   |        |
|-----------------------------------------------------------------------------------|--------|
| Door F L, Scratch(es), LI - Repair and paint (complete)                           | 318,35 |
|   |        |
| Door R L, Scratch(es), Acceptable                                                 | 0,00   |
| No pictures to display                                                            |        |
| Wheel cover F R, Scratch(es), Acceptable                                          | 0,00   |
| No pictures to display                                                            |        |
| Trunk lid covering R, Scratch(es), Acceptable                                     | 0,00   |
| No pictures to display                                                            |        |
| Door panel F L, Worn, Acceptable                                                  | 0,00   |
| No pictures to display                                                            |        |
| Wing R L, Scratch(es), Acceptable                                                 | 0,00   |
| No pictures to display                                                            |        |
| Bumper F, Scratch(es), LI - Repair and paint (complete)                           | 211,80 |
|  |        |
| Ignition key, Missing, E - Replace                                                | 150,00 |
| No pictures to display                                                            |        |