


BMW 5: 1HUB004

Vinnumber:	WBA5L11000D968719	Versionname:	5 TOURING 518da 150PK
First Registrationdate:	2/10/2014	Fiscalpower:	Aut.
Expertise Mileage:	142289	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 10000KM	Parking lot:	4513
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment
















Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	626,68
-------------------	--------

Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

		
Door F R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Rear spoiler, Chemical pollution, LI - Repair and paint (complete)		115,56
		
Bumper F L, Scratch(es), It - Spot repair		115,56
		
Parking sensor R, Missing, E - Replace		90,00
		
Sill outer R, Scratch(es), It - Spot repair		115,56
		
Roof, Scratch(es), 67 - Polish		0,00
<i>No pictures to display</i>		
Tailgate, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		