


**BMW 5: 1FOV823**

Vinnnumber:	<b>WBA5J31010D068106</b>	Versionname:	<b>5 TOURING 520dA 184PK</b>
First Registrationdate:	<b>10/09/2013</b>	Fiscalpower:	<b>Aut.</b>
Expertise Mileage:	<b>163970</b>	Power Kw:	<b>135</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>IN 22000KM</b>	Parking lot:	<b>3533</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/97 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Uniroyal: 5 mm</b>	Re.R.	<b>Uniroyal: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

**Total cost ex VAT** 1214,75

**Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)** 254,16




Rearview mirror housing R, Scratch(es), 67 - Polish

55,19



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Alloy rim F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Glove compartment lid, Scratch(es), Acceptable

0,00



Bumper F R, Scratch(es), It - Spot repair

115,56




Door R R, Scratch(es), Acceptable

0,00

*No pictures to display*

Rear window, Scratch(es), E - Replace

420,00



Roof pillar L, Scratch(es), Acceptable

0,00

*No pictures to display*