


MERCEDES A: 1GHT325

Vinnumber:	WDD1760111J230795	Versionname:	A 160 CDI 90PK
First Registrationdate:	11/02/2014	Fiscalpower:	
Expertise Mileage:	69109	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3705
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1454,98
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper trim R, Deformed / Strained, E - Replace	42,70



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Dent(s), PDR - Paintless dent repair	63,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Bumper R, Broken, Le - Replace and paint 651,00



GPS, Not functioning (well), P - Check 0,00



Wheel cover R L, Scratch(es), E - Replace 30,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Rust, LI - Repair and paint (complete) 301,68



Wheel cover F L, Broken, E - Replace 30,00



Wheel cover F R, Missing, E - Replace 30,00



Bumper grille F R, Deformed / Strained, E - Replace 32,40



Bumper grille F L, Deformed / Strained, E - Replace 32,40

