



| AUDI A1 SPORTBACK: 1PXN619 | | | |
|------------------------------------|--------------------------|--------------|---------------------|
| Vinnumber: | WAUZZZ8X5HB031888 | Versionname: | 1.4 TDI 66kW |
| First Registrationdate: | 6/10/2016 | Fiscalpower: | |
| Expertise Mileage: | 47858 | Power Kw: | 66 |
| Bodytype: | Hatchback | Body color: | Dark Blue |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2408 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | | | |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Luggage cover | |
| Windows electric F | | Rear parking sensors | |
| Windows electric R | | Type of Tow bar | No Tow bar |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | |
|----------------|----------------------------------|--------------------------|--|
| Summer tyres: | 185/60/15/84 H LightMetal | | |
| | Fr.L. | Fr.R. | |
| | Continental: 4 mm | Continental: 4 mm | |
| | Re.L. | Re.R. | |
| | Continental: 5 mm | Continental: 5 mm | |

| Assistance equipment | | | |
|---------------------------------------------------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 416,00 |
| Wing R R, Scratch(es), LI - Repair and paint (complete) | | | 246,56 |



| | | | |
|-----------------------------------|--|--|------|
| Door R R, Scratch(es), Acceptable | | | 0,00 |
|-----------------------------------|--|--|------|

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display