



AUDI Q5: 1FVA262

Vinnumber:	WAUZZ8R6EA030025	Versionname:	
First Registrationdate:	4/11/2013	Fiscalpower:	
Expertise Mileage:	167033	Power Kw:	120
Bodytype:	SUV	Body color:	Orange
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3122
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	55/55/19/101 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1750,06
Door R L, Scratch(es), LI - Repair and paint (complete)	382,02



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R R, Chemical polution, LI - Repair and paint (complete)	369,84
---	---------------



Door F L, Scratch(es), LI - Repair and paint (complete) 382,02



Tailgate, Chemical polution, LI - Repair and paint (complete) 362,02



Bumper F, Scratch(es), LI - Repair and paint (complete) 254,16



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), It - Spot repair 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display