



BMW 118 D HATCH: HZ5836

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------|
| Vinnnumber: | WBA1S51000V834621 | Versionname: | 2.0 118D (110KW) |
| First Registrationdate: | 29/09/2016 | Fiscalpower: | |
| Expertise Mileage: | 25887 | Power Kw: | 110 |
| Bodytype: | | Body color: | Dark Blue |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1304 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | No | | |

Options

| | | |
|--------------------------------|------------------------------|----------------------|
| Radio CD | | Seats electric F L |
| GPS storage | | Seats electric F R |
| GPS storage | HD | Central consol F |
| Windows electric F | | Luggage cover |
| Windows electric R | | Rear parking sensors |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting LED | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/50/17/89 W LightMetal | | | |
| Summer tyres: | Fr.L. | Bridgestone: 6 mm | Fr.R. | Bridgestone: 6 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

Assistance equipment

| | |
|---------|------------|
| Runflat | Yes |
|---------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 481,50 |
|-------------------|---------------|

| | |
|---------------------------------------|-------------|
| Maintenance book, Missing, Acceptable | 0,00 |
|---------------------------------------|-------------|



| | |
|--|-------------|
| Certificate Of Conformity, Missing, Acceptable | 0,00 |
|--|-------------|



| | |
|--|--------|
| Roof, Chemical pollution, LI - Repair and paint (complete) | 481,50 |
|--|--------|



| | |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display