

VOLKSWAGEN Golf: 1GA1053

Vinnumber:	WVWZZZAUZEP050807	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	5/12/2013	Fiscalpower:	
Expertise Mileage:	93914	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2409
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Type of Tow bar	No Tow bar
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	195/65/15/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 1,8 mm	Fr.R.	Michelin: 1,8 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1259,93
-------------------	---------

Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F R, Dent(s), LI - Repair and paint (complete)	318,35
---	--------



Door R L, Bad repair, Paint 0,00



Maintenance, Maintenance, Execute 0,00

No pictures to display

Wing R L, Bad repair, LI - Repair and paint (complete) 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Stain, Cleaning 75,00



Bumper R, Bad repair, Paint 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bad repair, Paint 0,00

