



**BMW X3: 1SXA879**

Vinnumber:	<b>WBAWZ310900F63807</b>	Versionname:	<b>X3 2.0d sDrive18 136PK</b>
First Registrationdate:	<b>1/10/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>96789</b>	Power Kw:	<b>100</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3121</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/60/17/99 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Pirelli: 2,5 mm</b>	Fr.R.	<b>Pirelli: 2,5 mm</b>
	Re.L.	<b>Firestone: 5 mm</b>	Re.R.	<b>Firestone: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>1971,68</b>
-------------------	----------------

Centre console, Tear, E - Replace	<b>313,00</b>
-----------------------------------	---------------



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Rocker panel inner F L, Scratch(es), Forfeit 115,56



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror R complete, Broken, Le - Replace and paint 307,00



Roof, Chemical pollution, LI - Repair and paint (complete) 577,80



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Tear, Acceptable 0,00




Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Seat cover R, Damaged, Acceptable 0,00



Bonnet, Chemical pollution, LI - Repair and paint (complete) 254,16



Door panel R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Bad repair, E - Replace	0,00

