



SKODA Superb: 1FRZ970

Vinnumber:	TMBJJ73T1E9024231	Versionname:	SUPERB COMBI GreenLine Ambition 105PK
First Registrationdate:	7/10/2013	Fiscalpower:	
Expertise Mileage:	170929	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3720
Maintenance:	PLUS 14600 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	909,04
Wing F L, Scratch(es), Acceptable	0,00



Door F L, Scratch(es), Acceptable

0,00



Tailgate, Repaired, No repair

0,00



Door F R, Bad repair, LI - Repair and paint (complete)

382,02



Seat cover F L, Stain, Cleaning

25,00



Alloy rim F L, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Seat cover F R, Stain, Cleaning

25,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Repaired, No repair

0,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Wing R L, Scratch(es), Acceptable

0,00



Door R R, Bad repair, LI - Repair and paint (complete)

382,02



Windscreen, Repaired, P - Check

0,00



Tires, Out of tolerance, P - Check

0,00



Wing R R, Bad repair, P - Check

0,00



Rearview mirror housing L, Scratch(es), Acceptable

0,00



Bonnet, Scratch(es), Acceptable

0,00

