


FORD Grand C-Max: 1FCT497

Vinnnumber:	WF0HXXWPBHP33684	Versionname:	GR.C-MAX Titanium St/St 115PK
First Registrationdate:	27/05/2013	Fiscalpower:	
Expertise Mileage:	155807	Power Kw:	85
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2606
Maintenance:	CONTROLLER		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/16/93 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 494,52

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), 67 - Polish 0,00

No pictures to display

Sliding door R, Bad repair, P - Check 0,00



Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Internal Boot Lining R, Scratch(es), E - Replace 50,52



Door F L, Bad repair, P - Check 0,00



Rear Panel Internal Lining, Scratch(es), E - Replace 118,40



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Bad repair, P - Check 0,00



Door F L, Scratch(es), 67 - Polish 0,00

No pictures to display

Handbrake cover, Worn, Acceptable 0,00

No pictures to display

Door F R, Dent(s), Acceptable 0,00

No pictures to display

Roof rail L, Deformed / Strained, E - Replace 67,80



Roof, Dent(s), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), 67 - Polish	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Roof rail R, Deformed / Strained, E - Replace	67,80

