



<b>BMW 3: 1HXJ466</b>			
Vinnumber:	<b>WBA3D91070F407408</b>	Versionname:	<b>3 BER 316d 116PK</b>
First Registrationdate:	<b>21/10/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>153153</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1312</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
Radio CD	Central consol F
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Alarm	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>225/50/17/94 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Dunlop: 3 mm</b>	Fr.R.	<b>Dunlop: 3 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

<b>Assistance equipment</b>	
Repair kit	<b>Yes</b>

Total cost ex VAT	<b>1131,68</b>
Door F L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Bonnet, Bad repair, Acceptable	<b>0,00</b>



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Door panel F R, Scratch(es), Acceptable

0,00

*No pictures to display*

Bumper F, Dent(s), Acceptable

0,00

*No pictures to display*

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wing R L, Scratch(es), 67 - Polish

0,00

*No pictures to display*

Wing R R, Dent(s), PDR - Paintless dent repair

63,00



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18



Gear shift lever cover, Worn, Acceptable

0,00

*No pictures to display*