



BMW 5: 1FQQ415

Vinnumber:	WBA5J11080D335651	Versionname:	5 TOURING 518d 136PK
First Registrationdate:	25/09/2013	Fiscalpower:	
Expertise Mileage:	117382	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3602
Maintenance:	-230KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/17/97 W LightMetal			
Summer tyres:	Fr.L. Goodyear: 4 mm	Fr.R. Goodyear: 4 mm	
	Re.L. Goodyear: 3 mm	Re.R. Goodyear: 3 mm	

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1352,26
--------------------------	----------------

Alloy rim R R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Ceiling, Stain, Cleaning	25,00
---------------------------------	--------------



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display


Maintenance, Maintenance, Execute

0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

350,16



Wing F R, Chemical polution, LI - Repair and paint (complete)

264,21



Rearview mirror R complete, Scratch(es), Smart repair

110,64



Tailgate, Dent(s), Acceptable

0,00

No pictures to display