



AUDI A5: CU4058

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnumber: | WAUZZZ8TXDA079772 | Versionname: | A5 SB DPF Multitr.177PK Aut. |
| First Registrationdate: | 20/06/2013 | Fiscalpower: | |
| Expertise Mileage: | 161566 | Power Kw: | 130 |
| Bodytype: | | Body color: | Brown |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2322 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Luggage cover | |
| GPS storage | HD | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Xenon | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 245/40/18/93 Y LightMetal | | | | |
| Summer tyres: | Fr.L. | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------------|------------|
| Spare wheel | No | Compressor | No |
| Emergency spare wheel | Yes | Jack | Yes |
| Repair kit | No | Runflat | No |

| | |
|---|---------|
| Total cost ex VAT | 2286,22 |
| Roof, Dent(s) and scratch(es), LI - Repair and paint (complete) | 577,80 |



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Grill frame, Scratch(es), Forfeit 125,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Dent(s), PDR - Paintless dent repair

82,80



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display