



OPEL Insignia: 1GRB269

Vinnumber:	WOLGT6ES8E1071014	Versionname:	INSIGNIA BER ecoFLEX Cosmo 140PK
First Registrationdate:	4/04/2014	Fiscalpower:	
Expertise Mileage:	87028	Power Kw:	103
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3332
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1313,60
-------------------	----------------

Door F R, Scratch(es), 67 - Polish	50,00
------------------------------------	--------------



Wing R R, Scratch(es), 67 - Polish

50,00



Interior, Damaged, Acceptable

0,00




Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Hail damage, PDR - Hail

250,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Scratch(es), 67 - Polish

50,00





Bonnet, Hail damage, PDR - Hail

250,00



Bodywork, Damaged, Acceptable

0,00



Roof pillar R, Hail damage, PDR - Hail

25,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Roof pillar L, Hail damage, PDR - Hail

25,00

