



AUDI A1 SPORTBACK: 1PYC156

| | | | |
|------------------------------------|--------------------------|--------------|---------------------|
| Vinnumber: | WAUZZZ8X2HB032142 | Versionname: | 1.4 TDI 66kW |
| First Registrationdate: | 11/10/2016 | Fiscalpower: | |
| Expertise Mileage: | 40128 | Power Kw: | 66 |
| Bodytype: | Hatchback | Body color: | Blue |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4220 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|-------------------------------|----------------------|-------------------|
| Radio CD | | Rear parking sensors | |
| GPS storage | SD | Type of Tow bar | No Tow bar |
| GPS storage | | | |
| Windows electric F | | | |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 185/60/15/84 H LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 5 mm | Fr.R. | Continental: 5 mm |
| | Re.L. | Continental: 7 mm | Re.R. | Continental: 7 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| | | Jack | Yes |

| | |
|--|--------|
| Total cost ex VAT | 999,02 |
| Bumper F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Tailgate, Dent(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |




Tyre F R, Tear, E - Replace 110,40




Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 232,06



Roof, Hail damage, PDR - Hail 125,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 169,44



Rocker panel inner F R, Dent(s), LI - Repair and paint (complete) 115,56

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 246,56



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Dent(s), Acceptable 0,00

No pictures to display