



VOLKSWAGEN Golf: 1HYP524

Vinnumber:	WVWZZZAUZFP517456	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	30/10/2014	Fiscalpower:	
Expertise Mileage:	110565	Power Kw:	77
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1411
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 V Steel				
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1959,18
-------------------	----------------

Wheel cover F R, Scratch(es), E - Replace	30,00
---	--------------



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Roof, Chemical pollution, Acceptable 0,00



Door F R, Dent(s) and scratch(es), Acceptable 0,00



Door F R, Scratch(es), Acceptable 0,00



Bumper grille F R, Scratch(es), Acceptable 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20




Luggage space cover, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Dashboard, Damaged, Acceptable 0,00




Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18





Wheel cover F L, Scratch(es), E - Replace

30,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35

