



TOYOTA AURIS: YX7352

Vinnumber:	SB1MS3JE20E299036	Versionname:	1.8 HYBRID DESIGN NAV BUSINESS AUTO
First Registrationdate:	12/01/2017	Fiscalpower:	
Expertise Mileage:	46377	Power Kw:	100
Bodytype:	Hatchback	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	4407
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2715,91
-------------------	---------

Roof pillar R, Hail damage, PDR - Hail	175,00
--	--------



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80




Wing F R, Hail damage, PDR - Hail 25,00



Interior, Stain, Cleaning 25,00



Wing F L, Chemical pollution, LI - Repair and paint (complete) 220,18



Wing R R, Hail damage, PDR - Hail 50,00



Roof pillar L, Hail damage, PDR - Hail 200,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Hail damage, LI - Repair and paint (complete) 530,08



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00

No pictures to display

Roof, Hail damage, LI - Repair and paint (complete) 865,50

