



TOYOTA AURIS: 1PYA442

Vinnumber:	SB1MS3JE90E281679	Versionname:	1.8 HYBRID LOUNGE CVT AUTO
First Registrationdate:	10/10/2016	Fiscalpower:	
Expertise Mileage:	37176	Power Kw:	73
Bodytype:		Body color	BLEU
Gearbox:	Automatic	Body color	Blue
Transmission:	Front	Paint type	Metalic
Fueltype:	Hybrid Petrol	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5	Parking lot	1412
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Level control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/91 W LightMetal				
Summer tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	576,36
-------------------	---------------

Parking sensor R, Missing, E - Replace	107,00
--	---------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Dent(s), PDR - Paintless dent repair

63,00



Bumper R, Stone chip(s), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair

82,80



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Interior, Dirty, Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Dent(s), It - Spot repair

115,56



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable

0,00

No pictures to display

Cigar lighter, Incomplete, E - Replace

18,00

No pictures to display

Door R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
Door F L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	