



VOLKSWAGEN POLO: 1JXP954

Vinnnummer:	WVWZZZ6RZFY263007	Versionname:	1.4 TDI 66KW TRENDLINE BMT
First Registrationdate:	13/03/2015	Fiscalpower:	
Expertise Mileage:	84395	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2502
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

175/70/14/84 T Steel				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			363,57
Seat cover F L, Stain, Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Repaired, Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Dent(s), PDR - Paintless dent repair			63,00



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Crack, Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), PDR - Paintless dent repair 82,80



Seat cover R R, Stain, Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Acceptable 0,00

No pictures to display

Rear bulkhead lining, Scratch(es), E - Replace 48,33



Wing F R, Chemical polution, Acceptable 0,00

No pictures to display

Wing F L, Chemical polution, 67 - Polish 0,00

No pictures to display

Floor covering F L, Burned, Acceptable 0,00

No pictures to display

Roof, Chemical polution, 67 - Polish 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 169,44

