



BMW 3: 1HFL190

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber: | WBA3K91030F935257 | Versionname: | 3 TOURING 316d 116PK |
| First Registrationdate: | 8/07/2014 | Fiscalpower: | |
| Expertise Mileage: | 74202 | Power Kw: | 85 |
| Bodytype: | Break | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OVER 7000 KM | Parking lot: | 2118 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|------------------|-------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Type of Tow bar | No Tow bar |
| GPS storage | HD | | |
| Windows electric F | | | |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS base | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|-------------------------|-------|-------------------------|
| 205/60/16/92 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Vredestein: 6 mm | Fr.R. | Vredestein: 6 mm |
| | Re.L. | Vredestein: 6 mm | Re.R. | Vredestein: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 716,60 |
|-------------------|---------------|

| | |
|---|---------------|
| Ignition key, Not functioning (well), E - Replace | 150,00 |
|---|---------------|



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80



Bodywork, Damaged, Acceptable

0,00



Interior, Damaged, Acceptable

0,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00

