



MERCEDES A: 1GSI484

Vinnumber:	WDD1760121J268881	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	15/04/2014	Fiscalpower:	
Expertise Mileage:	103019	Power Kw:	80
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4715
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection


Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			958,79
Door R R, Bad repair, LI - Repair and paint (complete)			318,35



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R L, Scratch(es), I - Repair

100,00



Roof, Dent(s), Acceptable

0,00

No pictures to display

Floor covering R, Burned, Smart repair

64,32



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), I - Repair

100,00



Bumper F M, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), I - Repair

100,00



Door frame R R, Dent(s), Acceptable

0,00

No pictures to display

Seat cover F L, Worn, Acceptable

0,00

No pictures to display

Floor covering F L, Burned, Smart repair

64,32

