



TOYOTA Hilux: 406BYY			
Vinnumber:	AHTFR22G806026108	Versionname:	HILUX 4WD Double Cab S 144PK
First Registrationdate:	27/08/2010	Fiscalpower:	
Expertise Mileage:	118788	Power Kw:	106
Bodytype:	Off-road	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	4 Weel	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3620
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options			
Windows electric F		Central consol F	
Windows electric R		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	No climate control		

Limited Technical Inspection			
Airco functioning	NOT OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/80/16/104 T LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Other: 3 mm	Re.R.	Other: 3 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			3601,31
Bodywork, Damaged, 67 - Polish			0,00
<i>No pictures to display</i>			
Interior, Dirty, Shampooing			200,00





Radio, Missing, E - Replace 210,00



Bodywork, Glue residues, Remove lettering 0,00



Steering wheel, Worn, Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), It - Spot repair 115,56



Bumper F R, Scratch(es), It - Spot repair 115,56



Door R R, Scratch(es), LI - Repair and paint (complete) 238,76



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Floor covering F L, Tear, E - Replace 237,00



Sill outer L, Dent(s), PDR - Paintless dent repair

63,00



Seat cover F L, Tear, E - Replace

300,00



Rear window, Broken, E - Replace

570,00



Glove compartment lid, Broken, E - Replace

228,00



Roof, Rust, LI - Repair and paint (complete)

361,13



Boot cover, Scratch(es), E - Replace

500,00

