



PEUGEOT EXPERT TEPEE: 1KPD613

Vinnumber:	VF3XDAHY8FZ028661	Versionname:	2.0 L2H1 72KW TEPEE ACCESS 6 PL
First Registrationdate:	8/06/2015	Fiscalpower:	
Expertise Mileage:	55719	Power Kw:	72
Bodytype:		Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV28
Number of doors:	5		
Number of seats:	8		
Number head rests:	8		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Rear parking sensors
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/101 T Steel			
Summer tyres:	Fr.L.	Fr.R.	Michelin: 5 mm
	Re.L.	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	844,20
-------------------	--------

Bonnet, Dent(s), LI - Repair and paint (complete)	217,56
---	--------





Seat cover R R, Deformed / Strained, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover R L, Deformed / Strained, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F R, Deformed / Strained, Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Damaged, E - Replace	300,00



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Inner door handle R R, Broken, E - Replace	33,00



Door trim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Inner door handle R L, Broken, E - Replace	33,00



Bumper corner R L, Scratch(es), Smart repair	110,64
--	--------



Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Floor covering F L, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Dashboard, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	