



LAND ROVER Evoque: 1FU1999

Vinnumber:	SALVA2BC5DH842936	Versionname:	EVOQUE TD4 4WD Pure 150PK Aut.
First Registrationdate:	28/10/2013	Fiscalpower:	
Expertise Mileage:	51089	Power Kw:	110
Bodytype:		Body color:	Red
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3531
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/60/18/107 V LightMetal				
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2093,57
--------------------------	----------------

Windscreen, Tear, E - Replace	0,00
--------------------------------------	-------------



Interior, Dirty, Cleaning 0,00

No pictures to display

Door F L, Chemical polution, LI - Repair and paint (complete) 382,02



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F M, Deformed / Strained, Smart repair 110,64



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel arch cover F L, Scratch(es), E - Replace 198,00

No pictures to display

Bumper corner R L, Dent(s) and scratch(es), It - Spot repair 115,56



Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Bumper corner R R, Scratch(es), It - Spot repair 115,56



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Spoiler F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair 115,56



Bumper F L, Scratch(es), It - Spot repair 115,56



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56

