



FORD Galaxy: 1HUB009

Vinnumber:	WF0MXXGBWMEB00375	Versionname:	GALAXY ECO Tit.Style DPF 136PK
First Registrationdate:	2/10/2014	Fiscalpower:	
Expertise Mileage:	156208	Power Kw:	100
Bodytype:	MPV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2730
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 Y LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Other: 6 mm	Re.R.	Other: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2827,58
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)			382,02



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Tailgate, Bad repair, LI - Repair and paint (complete)

362,02



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Bad repair, E - Replace

483,84



Bumper F, Dent(s), Acceptable

0,00

No pictures to display

Door R L, Dent(s), Acceptable

0,00

No pictures to display

Wing F L, Dent(s), Acceptable

0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R R, Bad repair, LI - Repair and paint (complete)

382,02



Luggage space cover, Missing, E - Replace

288,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84

