



RENAULT CAPTUR: 1NLR062

Vinnumber:	VF12RBJ1A54881593	Versionname:	1.5 ENERGY DCI 90 EXTREM ECO2
First Registrationdate:	18/03/2016	Fiscalpower:	
Expertise Mileage:	37180	Power Kw:	66
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3827
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/17/91 V LightMetal				
Summer tyres:	Fr.L.	Kumho: 6 mm	Fr.R.	Kumho: 6 mm
	Re.L.	Kumho: 7 mm	Re.R.	Kumho: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	205,64
-------------------	---------------

Alloy rim R R polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper corner R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper F R, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Bumper cover R M, Scratch(es), Smart repair	110,64
---	--------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

