



AUDI A3: 1FK0077

Vinnumber:	WAUZZZ8V3EA030349	Versionname:	A3 SB Attraction 105PK
First Registrationdate:	29/07/2013	Fiscalpower:	
Expertise Mileage:	125549	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2411
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

GPS storage		Sun Roof electric	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 M-S LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1488,23
-------------------	---------

Tailgate, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Bad repair, Paint	0,00
-----------------------------	------



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing F L, Repaired, No repair 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08



Door R R, Bad repair, Paint 0,00




Interior, Dirty, Cleaning 100,00




Roof, Dent(s), Acceptable 0,00

No pictures to display

Door F R, Bad repair, Paint 0,00



Wing R L, Chemical polution, LI - Repair and paint (complete) 308,20



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Bad repair, LI - Repair and paint (complete) 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bad repair, LI - Repair and paint (complete) 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 259,80

