



OPEL Astra: 1FT0015

Vinnumber:	WOLPC6EA5EG016704	Versionname:	ASTRA BER ecoFLEX Essentia S&S 95PK
First Registrationdate:	21/10/2013	Fiscalpower:	
Expertise Mileage:	77714	Power Kw:	70
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3110
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/95 V Steel				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1200,62
-------------------	---------






Bumper F R, Scratch(es), It - Spot repair	115,56
---	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Ignition key, Missing, F - Replace	150,00
------------------------------------	--------

<i>No pictures to display</i>		
Bumper corner R R, Scratch(es), It - Spot repair		115,56
		
Door F L, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bodywork, Glue residues, Remove lettering		0,00
<i>No pictures to display</i>		
Bumper corner R L, Scratch(es), Acceptable		0,00
		
Roof pillar R, Dent(s), PDR - Paintless dent repair		82,80
		
Rocker panel inner R L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Rust, LI - Repair and paint (complete)		318,35
		
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Protection plate M, Hole, E - Replace		100,00
		
Rocker panel inner F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Chemical pollution, LI - Repair and paint (complete)		318,35
