


SKODA Octavia: 1FXK505

Vinnumber:	TMBJG9NE8E0107796	Versionname:	OCTAVIA COMBI Elegance 105PK
First Registrationdate:	27/11/2013	Fiscalpower:	
Expertise Mileage:	141367	Power Kw:	77
Bodytype:		Body color	Brown
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4831
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/45/17/94 Y LightMetal			
	Fr.L.	Firestone: 7 mm	Fr.R.	Firestone: 7 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	No
Total cost ex VAT			1128,83
Wing R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)			318,35



Sill outer L, Dent(s), PDR - Paintless dent repair

178,80




Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), It - Spot repair

115,56



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair

115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F R, Scratch(es), It - Spot repair

115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Compressor, Missing, E - Replace

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Interior, Dirty, Cleaning

0,00

