


**RENAULT Captur: 1HRN638**

|                                    |                          |              |                                    |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnumber:                         | <b>VF12RFL1H51480999</b> | Versionname: | <b>CAPTUR Energy Business 90PK</b> |
| First Registrationdate:            | <b>15/09/2014</b>        | Fiscalpower: |                                    |
| Expertise Mileage:                 | <b>179240</b>            | Power Kw:    | <b>66</b>                          |
| Bodytype:                          | <b>SUV</b>               | Body color:  | <b>Black</b>                       |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                     |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>                   |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                          |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2305</b>                        |
| Number of doors:                   | <b>5</b>                 |              |                                    |
| Number of seats:                   | <b>5</b>                 |              |                                    |
| Number head rests:                 | <b>5</b>                 |              |                                    |
| Rims summer:                       | <b>Aluminium</b>         |              |                                    |
| Category:                          | <b>Passenger Car</b>     |              |                                    |
| Oil level:                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                    |

**Options**

|                                |                               |
|--------------------------------|-------------------------------|
| Windows electric F             | Luggage cover                 |
| Windows electric R             | Rear parking sensors          |
| Cruise Control                 | Type of Tow bar               |
| Steering wheel multifunctional | <b>No Tow bar</b>             |
| Radio multimedia               |                               |
| Type of headlighting           | <b>Headlighting Halogen</b>   |
| Type of GPS                    | <b>GPS big screen color</b>   |
| Type of Lining                 | <b>Lining fabrics</b>         |
| Type of climate control        | <b>Manual climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/60/16/92 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Michelin: 6 mm</b> | Fr.R. | <b>Michelin: 6 mm</b> |
|               | Re.L.                            | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|  |               |
|--|---------------|
| Total cost ex VAT  | <b>190,00</b> |
| Alloy rim F L, Scratch(es), Acceptable                       | <b>0,00</b>   |
| <i>No pictures to display</i>                                |               |
| Bumper R, Scratch(es), Acceptable                            | <b>0,00</b>   |
| <i>No pictures to display</i>                                |               |
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b>  |



|  |       |
|--|-------|
| Door F L, Dent(s) and scratch(es), Acceptable                | 0,00  |
| <i>No pictures to display</i>                                |       |
| Door F R, Scratch(es), Acceptable                            | 0,00  |
| <i>No pictures to display</i>                                |       |
| Door R R, Scratch(es), Acceptable                            | 0,00  |
| <i>No pictures to display</i>                                |       |
| Wing F R, Scratch(es), Acceptable                            | 0,00  |
| <i>No pictures to display</i>                                |       |
| Alloy rim F R, Scratch(es), Acceptable                       | 0,00  |
| <i>No pictures to display</i>                                |       |
| Wing F L, Scratch(es), Acceptable                            | 0,00  |
| <i>No pictures to display</i>                                |       |
| Bumper F, Scratch(es), Acceptable                            | 0,00  |
| <i>No pictures to display</i>                                |       |
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | 95,00 |

