



BMW X5: XC8677

Vinnumber:	WBAKS210000K85146	Versionname:	X5 2.0dA xDrive25 218PK Aut.
First Registrationdate:	30/09/2014	Fiscalpower:	
Expertise Mileage:	165748	Power Kw:	160
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	NOT OK
Maintenance	24/01/2019	Parking lot:	TRU17
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	NOT OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	No
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	NOT OK
Exhaust gass	NOT OK	Wiper fluid level	OK
Handbrake	OK	Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

255/55/18/109 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	370,68
-------------------	---------------

Door R R, Dent(s) and scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)	115,56
---	---------------



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 0,00

No pictures to display

Rocker panel inner F R, Dent(s), LI - Repair and paint (complete) 115,56



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Boot carpet, Damaged, Repair/replace (lump sum) 24,00



Electricity circuit, Not functioning (well), Diagnosis 0,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Engine, Not functioning (well), Diagnosis 0,00

