



**BMW 3 TOURING: 1JXJ583**

|                                    |                          |              |   |
|------------------------------------|--------------------------|--------------|---|
| Vinnumber:                         | <b>WBA3L11070K177574</b> | Versionname: | <b>2.0 320D EFFICIENTDYN. (120KW) TOURING</b> |
| First Registrationdate:            | <b>12/03/2015</b>        | Fiscalpower: |   |
| Expertise Mileage:                 | <b>78646</b>             | Power Kw:    | <b>120</b>                                    |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Black</b>                                  |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                                |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                              |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                     |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>2725</b>                                   |
| Battery functioning:               | <b>Yes</b>               |              |   |
| Number of doors:                   | <b>5</b>                 |              |   |
| Number of seats:                   | <b>5</b>                 |              |   |
| Number head rests:                 | <b>5</b>                 |              |   |
| Rims summer:                       | <b>Aluminium</b>         |              |   |
| Category:                          | <b>Passenger Car</b>     |              |   |
| Oil level:                         | <b>OK</b>                |              |   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |   |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Sun Roof electric            |
| GPS storage                    | Panoramic roof               |
| GPS storage                    | <b>HD</b> Central consol F   |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Front parking sensors        |
| Cruise Control                 | Rear parking sensors         |
| Steering wheel multifunctional |                              |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**


|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>205/60/16/92 H LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                            | <b>Goodyear: 6 mm</b> | Fr.R. | <b>Goodyear: 6 mm</b> |
|               | Re.L.                            | <b>Goodyear: 6 mm</b> | Re.R. | <b>Goodyear: 6 mm</b> |

**Assistance equipment**

|   |            |            |               |
|---|------------|------------|---------------|
| Repair kit                                    | <b>Yes</b> | Compressor | <b>Yes</b>    |
| Total cost ex VAT                             |            |            | <b>801,68</b> |
| Wing R R, Dent(s) and scratch(es), Acceptable |            |            | <b>0,00</b>   |



Engine protective plate, Deformed / Strained, E - Replace 100,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Bonnet, Stone chip(s), Acceptable 0,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18

