



HYUNDAI ix35: 1GPU476

Vinnumber:	TMAJU81UAEJ571628	Versionname:	ix35 2WD Executive 115PK
First Registrationdate:	27/03/2014	Fiscalpower:	
Expertise Mileage:	127847	Power Kw:	85
Bodytype:	SUV	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2404
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
	No Tow bar

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/5/18/98 V LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2355,67
-------------------	----------------

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)

115,56



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Stone chip(s), Acceptable

0,00

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable

0,00

No pictures to display

Door moulding Lower F R, Scratch(es), E - Replace

114,00



Certificate Of Conformity, Missing, E - Replace

150,00

No pictures to display

Bumper R, Scratch(es), Smart repair

110,64



Door moulding Lower R R, Scratch(es), E - Replace

114,00





Sill outer R, Scratch(es), It - Spot repair

115,56



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Floor covering F L, Hole, E - Replace

252,00



Bumper R, Broken, LI - Repair and paint (complete)

211,80



Seat cover F L, Worn, Acceptable

0,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Luggage space cover, Missing, E - Replace

240,00

