



FORD Galaxy: 1JGT241			
Vinnumber:	WF0MXXGBWMEG18109	Versionname:	GALAXY Trend Style St/St DPF 115PK
First Registrationdate:	15/12/2014	Fiscalpower:	
Expertise Mileage:	110499	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4710
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT		316,28
Bumper cover R M, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Outer backrest protection R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		

<i>No pictures to display</i>		
Door F R, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Roof, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Outer backrest protection L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Ceiling, Stain, Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Repaired, Acceptable		0,00
<i>No pictures to display</i>		
Glove compartment lid, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00



Internal Boot Lining R, Scratch(es), Smart repair		110,64
---	--	--------



Bumper corner R L, Repaired, Acceptable		0,00
<i>No pictures to display</i>		
Tires, Not original part, Acceptable		0,00
<i>No pictures to display</i>		
Bumper F, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Trunk lid covering R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Centre console, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Internal Boot Lining L, Scratch(es), Smart repair		110,64

