



<b>BMW 3: 1FE060</b>			
Vinnumber:	<b>WBA3K11080F852568</b>	Versionname:	<b>3 TOURING 318dA 136PK Aut.</b>
First Registrationdate:	<b>7/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>165522</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2427</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Sun Roof electric	
GPS storage	<b>HD</b>	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		
Sport seats			

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>			
Winter tyres:	<b>225/50/17/98 H LightMetal</b>		
	Fr.L.	<b>Goodyear: 6 mm</b>	Fr.R.
	Re.L.	<b>Uniroyal: 6 mm</b>	Re.R.
		<b>Goodyear: 6 mm</b>	<b>Uniroyal: 6 mm</b>

<b>Assistance equipment</b>			
Spare wheel	<b>No</b>	Compressor	<b>No</b>
Emergency spare wheel	<b>No</b>	Jack	<b>No</b>
Repair kit	<b>No</b>	Runflat	<b>No</b>

<b>Total cost ex VAT</b>	<b>2236,91</b>
<b>Bumper R, Deformed / Strained, Le - Replace and paint</b>	<b>651,00</b>



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Tyre F R, Tear, E - Replace 132,00



Interior, Dirty, Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 366,35



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Tear, Acceptable 0,00



Rearview mirror R complete, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete) 115,56




Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Side window trim R R, Missing, E - Replace 17,00

