



**IVECO Daily 40C15: 1BVZ466**

Vinnumber:	<b>ZCFC40A4205852908</b>	Versionname:	<b>DAILY B/F 40C15V LWB H2 146pk 3500KG</b>
First Registrationdate:	<b>16/09/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>157986</b>	Power Kw:	<b>107</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>TRU17</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Type of Tow bar	<b>Tow bar fixed</b>
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>No GPS</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>No climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>195/75/16/107 R Steel</b>				
Summer tyres:	Fr.L.	<b>Uniroyal: 6 mm</b>	Fr.R.	<b>Uniroyal: 6 mm</b>
	Re.L.	<b>Bridgestone: 3 mm</b>	Re.R.	<b>Bridgestone: 3 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	3255,54
-------------------	---------

Molding trunk, Strained , Smart repair	110,64
--	--------



Seat cover F R, Damaged, E - Replace	300,00
--------------------------------------	--------



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 165,13



Bumper R, Deformed / Strained, E - Replace 329,40



Windscreen, Scratch(es), E - Replace 395,40



Door R L, Rust, Acceptable 0,00

No pictures to display

Rearview mirror L complete, Broken, E - Replace 138,00



Sidewall RR (LCV), Rust, Acceptable 0,00

No pictures to display

Molding trunk, Strained , Smart repair 110,64



Glove compartment lid, Broken, E - Replace 228,00



Seat cover F L, Damaged, E - Replace 300,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 158,85







Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)

361,13



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Rearview mirror R complete, Broken, E - Replace

138,00



Trunk door R L, Dent(s) and scratch(es), It - Spot repair

115,56



Sidewall RL (LCV), Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair

63,00



Bumper F, Scratch(es), Smart repair

110,64



Maintenance book, Missing, E - Replace

0,00

No pictures to display