



MERCEDES C: 1GGS203

Vinnumber:	WDD2040001G171532	Versionname:	C BER 180 CDI BlueEFF. S&S 120PK
First Registrationdate:	4/02/2014	Fiscalpower:	
Expertise Mileage:	196249	Power Kw:	88
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3313
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather and alcantara
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/94 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 8 mm	Fr.R.	Bridgestone: 8 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1421,69
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00





Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Roof, Scratch(es), 67 - Polish

0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display


Backrest cover F L, Worn, Acceptable

0,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Door F L, Scratch(es), LI - Repair and paint (complete)

318,35



Rearview mirror glass R, Broken, E - Replace

18,00




Bumper grille, Deformed / Strained, Forfeit

0,00

No pictures to display

Bonnet, Dent(s), LI - Repair and paint (complete)

290,08





Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 290,08



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00

