



SKODA FABIA COMBI: 1LED116

Vinnumber:	TMBJJ6NJ5GZ051280	Versionname:	1.4 CRTDI 66KW AMBITION
First Registrationdate:	2/09/2015	Fiscalpower:	
Expertise Mileage:	121440	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	No		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Windows electric F		Central consol F
Type of headlighting	Headlighting Halogen	Luggage cover
Type of Lining	Lining fabrics	Rear parking sensors
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	No
Tires wear profile	OK	Power steering	No
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	NOT OK
Exhaust gass	NOT OK	Wiper fluid level	OK
Handbrake	OK	Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/60/15/92 H LightMetal				
Summer tyres:	Fr.L.	Other: 3 mm	Fr.R.	Other: 3 mm
	Re.L.	Other: 4 mm	Re.R.	Other: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1142,90
Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Damaged, Smart repair	64,32



Bonnet, Dent(s), LI - Repair and paint (complete) 232,06



Wing R R, Dent(s), Acceptable 0,00

No pictures to display

Door R R, Dent(s), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 278,68



Engine, Not functioning (well), Diagnosis 0,00

No pictures to display

Sill outer R, Rust, LI - Repair and paint (complete) 248,40

