



VOLKSWAGEN CADDY: 1JVE609

Vinnnumber:	WV2ZZZ2KZFX106242	Versionname:	1.6 TDI 75KW DSG MAXI DARK & COOL
First Registrationdate:	4/03/2015	Fiscalpower:	
Expertise Mileage:	161827	Power Kw:	75
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2206
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/94 H Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1977,39
Wing F R, Scratch(es), LI - Repair and paint (complete)	0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Wheel cover R R, Scratch(es), Acceptable

0,00

No pictures to display


Roof, Chemical polution, Acceptable

0,00

No pictures to display

Tailgate, Dent(s), LI - Repair and paint (complete)

362,02



Bumper R, Scratch(es), LI - Repair and paint (complete)

158,85



Bonnet, Chemical polution, LI - Repair and paint (complete)

217,56



Wing R L, Scratch(es), LI - Repair and paint (complete)

231,15



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Wheel cover F R, Scratch(es), E - Replace

22,50





Bumper F, Scratch(es), LI - Repair and paint (complete) 158,85



Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete) 478,02



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display